

OXcon™

Oxalic Acid



Mix one (1) part OXcon with four (4) parts water for use.

Diluted OXcon is designed to remove metallic discolorations as well as to brighten up wood surfaces that have turned dark from the use of high pH (alkaline) cleaners and strippers. OXcon should not be used to remove grayed wood fibers. Wood ReNew™ works best for removing grayed UV damaged surface wood.

Recommended Applications:

- ≅ To remove discolorations due to the presence of metallic tannates and rust.
- ≅ To brighten the wood after the use of high pH strippers and cleaners.
- ≅ To even out the color of a wall that's blotchy.

Do not use OXcon to:

- ≅ Remove grayed wood.
- ≅ "Neutralize" the wood after the use of other chemicals.
- ≅ To remove brown stain, blue stain or flavonoid discolorations.

**PERMA-CHINK®
SYSTEMS, INC.**

www.permachink.com

1.0 gallon (approx. 3.8 liters)

3/09

APPLICATION DIRECTIONS

Surface Preparation: Brush or wipe off any extraneous debris that may be present. OXcon should only be applied to clean, bare wood surfaces.

Mixing: Dilute one (1) part OXcon with four (4) parts water in a clean plastic container. Do not use a metal container! OXcon must be properly diluted since higher concentrations can damage the wood surface. Mix thoroughly before using and periodically during use.

Application: OXcon may be applied with a low pressure sprayer, roller, brush, or broom. Use liberal amounts (a flooding coat) over an entire area. Do not spot-treat since this method of application can cause blotching. Allow the solution to remain on the surface for 10 to 15 minutes, then rinse thoroughly with lots of fresh water starting at the top of the wall and working your way down. Allow the surface to dry, then look at the results. If the wood is still too dark or blotchy, repeat the procedure.

Rinsing: It is extremely important that all OXcon residue be thoroughly rinsed off of the wood. We strongly recommend the use of pH Strips to assure that all OXcon residue has been removed

CAUTION

Keep out of reach of children. Wear protective breathing gear, rubber gloves, and eye protection. Make certain the work area is well ventilated. Do not breathe fumes and keep away from heat that could produce fumes. If exposed, promptly flush eyes with water and wash skin with soap and water. Cover plants, shrubs, aluminum frames, etc. before use.

LIMITED WARRANTY

Perma-Chink Systems, Inc. warrants and represents that Perma-Chink Systems Family of Products will conform to the description and specifications previously set forth and be free from defects in material and workmanship when shipped to the buyer. EXCEPT WHEN HEREIN EXPRESSLY STATED, THERE ARE NO WARRANTIES, EXPRESSED OR IMPLIED, BY OPERATION OF LAW OR OTHERWISE, APPLICABLE TO THE PERMA-CHINK LOG HOME PRODUCT. PERMA-CHINK SYSTEMS EXPRESSLY DISCLAIMS ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

**PERMA-CHINK®
SYSTEMS, INC.**
www.permachink.com

Eastern Division
1-800-548-3554

Western Division
1-800-548-1231

Colorado
1-800-433-8781

Montana
1-800-479-7090

Minnesota
1-877-244-6548

3/09